

## U.S. M1 Helmet – 3D Model Instructions

This model has 20 helmets mounted on a sprue.

Each attachment point is to the inside of the helmet to avoid disrupting the outside surface.

You may wish to put the assembly in the sun for a few hours to make sure it is UV cured.

You may wish to clean the assembly carefully using diluted Simple Green to remove any traces of the printing process. Carefully rinse the assembly.

Carefully cut all helmets off the sprues. The helmets are thin to maintain scale appearance.

Paint inside and outside to your desired color.

You may want to add a chinstrap after it is cemented to your figurine. You can have it hanging from both sides or connected under the chin.

2/2/2017

